

**From:** [Robert Werner](#)  
**To:** [glove@dot.state.tx.us](mailto:glove@dot.state.tx.us)  
**Subject:** San Jacinto River Waste Pits (06ZQ) - Aerial Photo Order  
**Date:** 09/15/2009 11:36 AM

---

Gary,

This email confirms EPA's purchase of the following six aerial photos from the TXDOT:

1. 1973 photo – breach very visible in this photo, clean straight line makes breach look like it was man made breach, whole area is flooded bank to bank, photo dated 5/30/73, dike is flooded over but can see vegetation out of water from tops of dykes.
2. 1976 - area not flooded , breach visible.
3. 1980 - same breach but larger in size.
4. 1982 - area under water.
5. 1992 - north wall is under water.
6. 2000 - about ½ of east wall is gone.

Cost for all six photos plus shipping is \$228.00

Please mail the above prints to the following address:

U.S. Environmental Protection Agency  
Region 6, 6SF-TE, (Werner)  
1445 Ross Avenue, 12th Floor  
Dallas, TX 75202-2733

Please call you have questions.

Bob Werner  
214.665.6724